PROFESSIONAL CORPORATION -

ᆟ

KICHES, MICKENZIE & HERBERT LLP

BARRISTERS & SOLICITORS *
PATENT & TRADE MARK AGENTS
PAUL HERBERT, R PH., B.SC., PHM., LL.B., J.D., Ph.D. = BRANT LATHAM, B.A.SC. (CHEM.ENG.), LL.B., P.ENG = DAN HITCHCOCK, B.ENG., LL B. *
GARY M. TRAVIS, B SC. (GEOL.), LL.B. JEFF PERVANAS, B.A.SC. (ENG.SCI.), LL.B. = MICHAEL ADAMS, BENG. (MECH ENG.), B.SC., J.D.= BOBBY ATHWAL, B.A.SC. (MECH.ENG.), M.A.SC., LL.B., J.D.* MICHAEL YUN, B.SC. (BIOCHÉM), J.D.* BYRON THOM, B.A.SC. (ENG.SC!.), LL.B.* MARTA TANDORI CHENG A. LEONARD GROVE (1930-2006)

SUITE 1800 2 BLOOR STREET EAST TORONTO, CANADA

M4W 3J5

June 14, 2011

TELEPHONE (416) 961-5000 **FAX** (416) 961-5081

E-MAIL riches@patents-toronto.com riches@riches.ca

CONTINUING THE PRACTICE OF GEORGE H RICHES AND ASSOCIATES ESTABLISHED 1887

Commissioner for Patents Office of Patent Publication P.O. Box 1450 Alexandria, VA 22313-1450 U.S.A.

By Facsimile Only RECEIVED (571) 273-8300 CENTRAL FAX CENTER No. of pages - 4 JUN 1 4 2011

Attention: **Certificate of Correction Branch**

> PHILLIPS, Stanley; PHILLIPS, Shirley and PHILLIPS, Andrew Re:

Patent in the U.S.A.

Serial No.

: 10/589148

Filing Date: March 3, 2005

Certificate

Patent No. Our Case

: 7943098 : P44606

Issue Date: May 17, 2011

Title

: Apparatus for Generating Ozone and/or

O1 Using a High Energy Plasma

of Correction

Discharge

Request for Certificate of Correction Under 35 USC §254 and 35 USC §255

Dear Sir:

Enclosed, please find form PTO/SB/44 setting out seven (7) errors for which a Certificate of Correction is requested.

The following errors are believed to be minor in nature and are not the fault of the Patent Office:

- i. The first error is at page 13, column 11, line 29 where the word "electrode" should read --electrodes--; as is introduced at column 11, line 15.
- ii. The second error is at page 13, column 12, line 1 where the term "fluid inlet" should read -- gas inlet --; as is identified in preceding independent claim 1 at column 11, line 27;
- iii. The third error is at page 13, wherein the word --comprising-- should occur at column 12, line 9 immediately following "ozone and O₁" to provide grammatical structure;
- iv. The fourth error is at page 13, wherein the words "spaced flow" should be deleted from column 12, line 36; as these words are understood as being superfluous and improperly included;

06/15/2011 HMARZI1 00000016 7943098

01 FC:1811

100.00 OP

- v. The fifth error is that at page 13, column 12, line 49 the term "pump" should read --supply--; as is used earlier in the claim, as for example in column 12, line 37; and
- vi. The sixth error is that at page 13, column 12, line 52 the term "pump" should read --supply--, as is used earlier in the claims, as for example in column 12, line 37.
- vii. The seventh error is at page 14, wherein the term "fluid outlet passage" at column 13, line 8 should read --fluid outlet--, as for example is used later in the claim in claim 20 at column 13, line 13.

The government fee of US \$100.00 for a Certificate of Correction of Applicant's Mistake under 35 USC §255 is enclosed herewith.

The Office is advised that the foregoing mistakes have been in good faith are not believed to constitute new matter, insofar as the corrections relate to the rectification of obvious antecedent and/or grammatical errors only.

Favourable consideration is respectfully requested.

Respectfully submitted,

PHILLIPS, Stanley; PHILLIPS, Shirley and PHILLIPS, Andrew

GMT/rf Enclosures Form PTO/SB/44 Form PTO-2038 - fee of \$100 Ret. Ack. Card

By: Cary M. Tra

Reg/No. 43,55

(Also Form PTO-1050)

Page <u>1</u> of <u>1</u>

PTO/SB/44 (09-07) Approved for use through 08/31/2013. OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

: 7943098 B2

FROM-Riches McKenzie & Herbert LLP

APPLICATION NO.: 10/589148

ISSUE DATE

: May 17, 2011

INVENTOR(S)

PHILLIPS, Stanley; PHILLIPS, Shirley and PHILLIPS, Andrew

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

column 11, line 29, "electrode" should read --electrodes--.

column 12, line 1, "fluid inlet" should read -gas inlet--.

column 12, line 9, "ozone and O1" should be changed to -ozone and O1 comprising--.

column 12, line 36, delete the text "spaced flow".

column 12, line 49, "pump" should be changed to --supply--. column 12, line 52, "pump" should be changed to --supply--. column 13, line 13, "fluid outlet passage" should read --fluid outlet--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Riches, McKenzie & Herbert LLP 2 Bloor Street East, Suite 1800 Toronto, Ontario, M4W 3J5

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS SEND TO: Attention Certificate of Corrections Branch Commissioner for Patents. P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria,

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.